

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 12/02 To (mo./yr.) 12/03
2. DOGM File Number (Mine No): 54 300 124
3. Mine Name: THE GOLDEN EMPRESS 1, 2, 3
4. Mineral(s) Mined (or permitted to mine): GOLD, SILVER & ASSOCIATED MINERALS
5. Type of mine ☐ Surface Mine or ☒ Underground Mine
6. Legal Description (Location of Lands Affected):
IN → NW 1/4, ___ 1/4, ___ 1/4, Section 32, Township 15, Range 7E
& IN ~~NE~~ 1/4, NE 1/4, ___ 1/4, Section 32, Township 15, Range 7E
___ 1/4, ___ 1/4, ___ 1/4, Section ___, Township ___, Range ___
7. Name of Operator or Company: JUNE BALACH
8. Permanent Street Address: 1766 WEST 4575 SO
City, State, Zip: ROY, UTAH 84067-3033
Phone: 801-731-2925 Fax: 801-731-8475
9. Company Representative (or designated operator):
Name: _____
Title: _____
Business Address: _____
City, State, Zip: _____
Phone: _____ Fax: _____
☐ Please check if any of the above information has changed since previous year.

RECEIVED

FEB 06 2004

DIV. OF OIL, GAS & MINING

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? _____
3. If yes - how much ore or mineral was mined? NO ORE MINED
FAKE OPERATION ONLY -

Claim
2

Pic's
ENCLOSED

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.
AT THE MAIN ADIT ENTRANCE THE HILL AT THE
NORTH WAS SLIGHTLY EXCAVATED SO THAT ALL
LOOSE ROCKS COULD BE WIRED AND BOTTED
ABOUT 400 YARDS WAS REMOVED
5. How much **additional acreage** was disturbed during the past year? 6% OF AN ACRE
6. How much acreage was **reclaimed** during the past year? 3% OF AN ACRE
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
THE ROCK REMOVED FROM THE ADIT FACE WAS
PLACED IN A DRAW JUST EAST OF THE ADIT
IT IS BEING COVERED WITH TOPSOIL AS
WE GO. EVALUATION - EXCELLANT.
8. What is the **total** disturbed acreage of entire project at years end? 2,600 Sq Ft
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.
CONTINUE TO LEVEL ROCK AND COVER WITH
FILLED TOPSOIL. AT A LATER DATE RESEED
PER FOREST SERVICE.

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information - R647-4-121.2 and .3

1. The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

JUNE Balaich

Title of Operator:

OWNER

Signature of Operator:

June Balaich
1/15/04

Date:

~~PHOTO~~


DUMP AREA

AREA CLEANED AND TOPSOIL PILED FOR RECLAMATION





LARGER VIEW



FACE OF THE MINE WIRED & BOLTED FOR SAFTEY



WILD TURKEYS BELOW THE MINE.